



**FortyEight™**  
**48V Low Glare Directional**  
**Recessed In-Track Linear Lighting**



Colour options:



Cat. No.	Watts	lm/W	Lumens	Colour	Beam
AA-FEV-DLU6*-30**	6W	80	480lm	3000K	24° / 36°
AA-FEV-DLU6*-40**	6W	80	480lm	4000K	24° / 36°
AA-FEV-DLU12*-30**	12W	83	1000lm	3000K	24° / 36°
AA-FEV-DLU12*-40**	12W	83	1000lm	4000K	24° / 36°
AA-FEV-DLU18*-30**	18W	83	1400lm	3000K	24° / 36°
AA-FEV-DLU18*-40**	18W	83	1400lm	4000K	24° / 36°

Black      White

\*Add 24° / 36° for beam angle

\*\*Add suffix **W** or **BLK** for White or Black finish


**Triac, Dali, 0-10V dimmable options available**, contact sales office for more information

**CRI80 as standard, CRI90 available on request**, contact sales office for more information




**FortyEight™**  
**48V Low Glare Directional**  
**Recessed In-Track Linear Lighting**

## Line Drawing



AA-FEV-DLU6      AA-FEV-DLU12      AA-FEV-DLU18  
(L) 112mm Length   (L) 220mm Length   (L) 328mm Length  
(W) 22mm Width   (W) 22mm Width   (W) 22mm Width  
(H) 10mm Height   (H) 10mm Height   (H) 10mm Height

## Polar Curves



## Product Features:

- Slick and stylish, minimalist, in-track, low glare linear luminaire
- Designed to fit in Aurora Africa 48V track
- CRI80 as standard, CRI90 available to order
- Works with surface mounted and recessed track options

## Product Specification:

Installation Type	Track
Input Voltage	48V
Luminaire Materials	Aluminium
Lifetime	50,000
CRI	80 & 90
IK Rating	IK10
IP Rating	IP20
Warranty	5 Years

## Warranty:

This product has a warranty period of 5 Years. Warranties may be available on certain products as indicated in the product description. Warranties are valid from the date of purchase. The warranty is invalid in the case of improper use, installation, tampering, removal of the Q.C. date label or installation in an improper working environment or installation. Should this product fail during the warranty period it will be replaced free of charge, subject to the correct installation of the original product and subsequent return of the faulty unit. Aurora does not accept responsibility for any installation costs associated with the replacement of this product and Aurora reserve the right to alter.